ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone DASARAHALLI	**Ward No.** 14	**Ward Name** Bagalakunte
Street ID W0337, W0366, W0364, W0368, W0527, W0335, W0343, W	**Street Name** NA, S Krishnappa Lyt, Lakshmi Sagar Lyt, 5th Crs, 1st Main Rd, 7th Crs Lakshmi Sagar Lyt	**Significant Landmark** Bagalagunte
Segment No. 14/C-W0337/S044901	**Total Length (m)** 426.06	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	27.10	77.501444	13.057771	77.501400	13.057530	9th Main	6th Main
2	87.54	77.500971	13.057582	77.501751	13.057387	9th Main	6th Main
3	33.12	77.501316	13.057855	77.501272	13.057559	3rd A cross	Samudaya Bhavana road
4	88.81	77.501006	13.057930	77.501817	13.057817	Maramma temple road	Venugopala swamy temple
5	95.50	77.501126	13.058977	77.501015	13.058120	Maramma temple road	Venugopala swamy temple
6	93.99	77.501358	13.058953	77.501242	13.058111	9th cross	6th main

Work Details

History of Road / Lane / Circles

Name of the Work Construction of drain and concrete work at karekallu and Bagalagunte Old Village Surroundings in ward No 14, Bagalagunte	**Sanctioned Estimated Amount (Rs.)** 10000000	**Sanctioned Year** 2018-19
Year 2018 - 2019	**Type of Work** Others	**Other Work Type** CC road and Drain
Tender Not a Tender	**Work Details**	**Job No. / Work Code** 014-19-000005
Work Order No. EE/DD/WO/365/18-19	**Work Order Date** 27/02/2019	**Period of Extention**
Defect Liability Period From 27/02/2019	**Defect Liability Period To** 26/02/2020	**Multiple road involved with the same Job No/ Work Code #** No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

Zone: DASARAHALLI Ward No: 14 Ward Name: Bagalakunte Street ID: W0337, W0366, W0364, W0368,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. 29.29 ಎಂ ಪಿ

Scanned by CamScanner

5000000.00

Technical manager(west)

Phone No.

9972373635

E-Mail ID

Field Inspection Details

Number of Trees	Any Other Information	Name
0	C C Road drain	Chetan KM
Date of Inspection	**Remarks**	
29/12/2020	work completed	

Category	Image	Photo Remark
Drain Condition		
Footpath Condition		
Road Condition		
Segment End		
Segment Start		

Remarks

Designation	Approver Name	Date	Target Date	Remark

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿ...
ಟಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿ...
ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎ
...ಳೂರು-೬೦

Zone: DASARAHALLI Ward No: 14 Ward Name: Bagalakunte Street ID: W0337, W0366, W0364, W0368,

Scanned by CamScanner